



OPERATOR INTERFACE PRODUCTS APPLICATION NOTE

Subject: SoftScreen 2000

AN# 1029A

Date: July 24, 1994

Name: Christopher J. Biernacki

Page: 1 of 1

Description: Convert 2000 Monochrome to 2050 Color

1. Create and save a new application configured to 2000 Color.
Make sure everything else about the new configuration matches the old.
- 6) Exit SoftScreen
- 7) At DOS prompt type SOFTMERGE
- 8) Go to SCREEN, and copy all mono screens to color application.
- 9) Quit SOFTMERGE
- 10) Restart SoftScreen
- 11) Enter color application
- 12) Create and save scratch screen with nothing on it
- 13) Go to first mono screen and cut entire screen
- 14) Go to scratch screen and paste
- 15) Check color palette and save under original name
- 16) Repeat for remaining screens

Keep in mind that this process will not transfer Function and Pseudo Keys.