



OPERATOR INTERFACE PRODUCTS APPLICATION NOTE

Subject: Chips & Technologies 65550 Refresh Rate Changes after Restart

AN#1063A

Date: 9/11/97

Name: Irvin Hayes Jr

Page 1 of 1

Description: SVGA Driver For Windows 95

SYMPTOMS

=====

When you change the refresh rate settings for your monitor on a computer using a Chips & Technologies 65550 video chip set, the settings may change back to the default settings when you restart the computer.

RESOLUTION

=====

To resolve this problem, follow these steps:

1. In Device Manager, double-click the Display Adapters branch to expand it.
2. Double-click the listed display adapter.
3. Click the Resources tab, and then click the Use Automatic Settings check box to clear it.
4. Click OK, and then click OK.
5. When you are prompted to restart your computer, do so.